FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School :

1. Name of the Officer : Arun Xavier. W
2. Location : Kottavattom, Punalur Edn subdistrict
3. Period for which the certificate is issued : 2022-2023
4. Types of building : Permanent R.C.C roof building
5. Nature of defect if any :
   - a) Foundation and basement : NIL
   - b) Superstructure : NIL
   - c) Doors and windows : NIL
   - d) Wood work wrought and put up : NIL
   - e) Roof : NIL
   - f) Flooring : NIL
   - g) Miscellaneous (Cracks if any) : NIL

   Ground floor - 1×64.3×8.5m×3.7m
   Verandha - 1×64.3×8.5m×3.7m
   First floor - 1×64.3×8.5×3.7m
   1×64.3×8.5×3.7m
   Second floor - 1×64.3×8.5×3.7m
   1×64.3×8.5×3.7m
   Stairlabin - 2×8.75×3.40×3.7m (ch from floor to)
6. Any Major defects notices which will render the building unsafe in any manner : NIL
7. Whether maintenance works have been done properly : yes
8. Whether the structure is sound or not for conducting classes : yes

Note:- 1. *The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.*
2. *Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.*

Structure is fit to conduct classes in normal weather condition.

CERTIFICATE

Certified that the School was inspected by me on 14-09-2022 and found to be fit / unfit to conduct classes for the period 2022-2023 for the reason stated above.

St. Francis Assisi CBSE School
Affiliation No. 931234
St. Francis Assisi School Road,
Elampal, Punalur, Kerala - 691322
Phone : 0475 2963 516, +91 7306 983 161
Email : assisischool@gmail.com
(Seal)

MANAGER
ST. FRANCIS ASSISI
ENGLISH MEDIUM SCHOOL
KOTTAVATTOM JUNCTION
ELAMPAL P.O.-691 322, PUNALUR

Place: Vilakkudi

Date: 14-09-2022

Assistant Engineer

ASSISTANT ENGINEER
L.S.G.D.
Vilakkudy Grama Panchayat